## Sample Gospel Hall

22 September 2005



# **Disability Access Audit**

For

Sample Gospel Hall



ARCHITECTURAL SERVICES

Droveway House 11 Lilac Avenue, Streetly Sutton Coldfield West Midlands B74 3TH

Tel: 0121 352 0150

www.droveway.co.uk

# Index **SECTION** Introduction 0 **External Approach Entrance & Reception** 2 **Horizontal Circulation** 3 **Vertical Circulation** Internal Spaces & Rooms 5 Aids to Communication 6 Sanitary Facilities 7 Means of Escape & Evacuation 8 Signage & Information 9 Care & Management 10 **Droveway Disability Access Audit**

Page 2

Sample Gospel Hall

#### **Horizontal Circulation**

Visual contrast with walls

Green door set in light timber panelling and light coloured wall provides good colour contrast

Visual contrast of front leading edge No visual contrast to leading edge of door. Recommend visual contrast applied to assist those with impaired sight

Pairs of doors

Not applicable. Single door.

Clear width

Clear width of 740mm is 10mm below clear width required for existing buildings.

As the clear width such a small amount below the required width, replacement may be as a low priority.
In the long term the aim should be to increase the clear width of the door to at least 750mm as required for existing buildings, or preferably to 800mm which would be required for new buildings.

**Threshold** 

Flush threshold

**Approach** 

There is a clear width of 270mm between the door edge and the adjoining wall on the pull side. Present regulations would require at least 300mm.

Recommend that when does replaced, a clear width of min 300mm is created.

Vision panels

Not provided. As this is a main through route circulation, it is recommended that when the door is replaced, it is fitted with a vision panel between 500 to 1200mm from floor, in safety glass

**Fully glazed doors** 

Not applicable. Not fully glazed

**Door furniture** 

ever handles at satisfactory height of 1010mm, but have no return end on handle, which aids those with limited grip.

Recommend handles replaced for those with return end

Colour contrast of furniture

Aluminium lever handles provide good visual contrast well with coldur of door

Door closers

Not fitted

Opening pressure

Satistactory low opening pressure.

If door closer is fitted in the future, consideration should be given to maintaining low opening pressure.

Additional Note

Many of the internal doors on a building such as this would need to be fire-resisting doors and frames to give protection to means of escape routes, if the property were to be constructed as new, including fire-resisting glass and self closing devices. If doors are replaced it would be prudent to consider whether the door should be upgraded to a fire-resisting door.

Internal **Door** Hall/







Droveway Disability Access Audit

Sample Gospel Hall Page 3

### **Internal Spaces & Rooms**

✓ Width of gangways / aisles

Loose furniture enables flexibility on gangway width.

For disabled access purposes, the recommended width of gangways and aisles is no less than 1200mm. The absolute minimum width for access to wheelchair spaces under Part M Building Regulations is 900mm.

However, width of aisles and escape routes is often governed by the requirements of Part Building Regulations which relate to means of escape, which require a clear width greater than that required for disabled access.

It is important that obstructions are not placed in gangways or aisles which would reduce the width to less than 1200mm for disabled access, or which would reduce the width of the aisle below that required for means of escape purposes.

Provision of wheelchair spaces within seating layout

Not applicable. No wheelchair access

Effect of wheelchairs on means of escape

Not applicable. No wheelchair access

Position of wheelchairs relative to activities

Not applicable. No wheelchair access

✓ Provision of space for an assistance dog

Assistance dogs can be accommodated by removal or adjustment of loose seating.

Please refer to notes at beginning of this section

√ Floor surfaces

Carpet to aisles, generally free from trip hazards at present. Some undulation in carpet fitting starting to be evident. This situation should be monitored to ensure trip hazards do not develop.

There are no differences in colours or patterns that could easily be mistaken for steps.

Hazards to partially sighted

Redundan loud speaker bracket at head height by door

✓ Acoustics

The from has reasonably god acoustics, free from echo and reverberation.

★ Seating styl

There are no seats with armrests.

Seats with arm rests can assist those with arthritis and those who have difficulty standing. Recommend that one or two seats with armrests are made available.

Natural & artificial lighting

Satisfactory natural and artificial lighting.

Natural lighting or glare from windows can be controlled by curtains. Stewards to monitor.

First \Floor





**Droveway Disability Access Audit** 

Sample Gospel Hall Page 4

### Sample only

Reproduction of this material

This material is copyright and must not be reproduced without the express permission of Droveway Architectural Services.

buildings

Arranging an Access Audit for your

Droveway will be happy to discuss your requirements with you. Call us on 0121 352 0150.

Copyright

© 2006 Droveway Architectural Services

**Droveway Disability Access Audit**